




























































**PERSVOETEN - PIEDS PRESSEUR - PRESSER FEET FOR JANOME TOP LOAD 2000-11000**

 <p><b>Ref : 200002008</b> Foot welding double Janome top loading</p> <p><b>077.002.008</b></p>	 <p><b>Ref : 200003102</b> Foot gathering Janome top load</p> <p><b>077.003.102</b></p>	 <p><b>Ref : 200005104</b> Foot pintuck Janome top load 7 groove - 7 rainures</p> <p><b>077.005.104</b></p>
 <p><b>Ref : 200008107</b> Foot 1/4" Janome 2000-9000</p> <p><b>077.008.107</b></p>	 <p><b>Ref : 200009108</b> Foot pintuck Janome groove top loading 5 groove - 5 rainures</p> <p><b>077.009.108</b></p>	 <p><b>Ref : 200017109</b> Foot fringe Janome 2000-7500</p> <p><b>077.017.109</b></p>
 <p><b>Ref : 200020105</b> Foot darning Janome 8000, 9000</p> <p><b>077.020.105</b></p>	 <p><b>Ref : 200034205</b> Foot hemmer 6mm. Janome 2000-10000</p> <p><b>077.034.205</b></p>	 <p><b>Ref : 200034308</b> Foot hemmer 4mm. Janome 2000-10000</p> <p><b>077.034.308</b></p>
 <p><b>Ref : 200203104</b> Foot blindhem Janome MyLock 134D- 204D-634D-644D-734D- 744D</p> <p><b>077.200.203</b></p>	 <p><b>Ref : 214504008</b> Foot walking Janome 8000, 9000, 10000, 5700</p> <p><b>077.214.504</b></p>	 <p><b>Ref : 214874013</b> Foot walking 7mm. Janome top load low</p> <p><b>077.214.874</b></p>
 <p><b>Ref : 214875014</b> Foot walking Janome low front load</p> <p><b>077.214.875</b></p>	 <p><b>Ref : 4021</b> Foot darning Janome low type</p> <p><b>077.004.021</b></p>	 <p><b>Ref : 685502008</b> Foot ZZ Janome 2014 "A". Also called the all purpose foot, used for most utility sewing from straight stitch to zigzag stitching.</p> <p><b>077.685.502</b></p>
 <p><b>Ref : 753801004</b> Foot buttonhole Janome sliding 3018/23, 3123, 4018, 4023, 8000</p> <p><b>077.753.801</b></p>	 <p><b>Ref : 802403007</b> Foot cording Janome 619-804</p> <p><b>077.802.403</b></p>	 <p><b>Ref : 802406000</b> Foot button Janome D sew-on</p> <p><b>077.802.406</b></p>
 <p><b>Ref : 802422002</b> Guide quilting Janome 6000"L</p> <p><b>077.802.422</b></p>	 <p><b>Ref : 804509000</b> Foot shank Janome 2000-7500 For top load - low shank</p> <p><b>077.804.509</b></p>	 <p><b>Ref : 820801005</b> Foot buttonhole Janome 6000</p> <p><b>077.820.801</b></p>
 <p><b>Ref : 820804019</b> Foot overlock Janome 6000</p> <p><b>077.820.804</b></p>	 <p><b>Ref : 820809014</b> Foot hemmer 1/8" Janome 6000 "D"</p> <p><b>077.820.809</b></p>	 <p><b>Ref : 820815002</b> Foot applique Janome 6000 "F"</p> <p><b>077.820.815</b></p>
 <p><b>Ref : 820819006</b> Foot cording Janome 6000 "H"</p> <p><b>077.820.819</b></p>	 <p><b>Ref : 820822013</b> Foot buttonhole 4-step Janome 2014/5/8/22, 5500, 6000</p> <p><b>077.820.822</b></p>	 <p><b>Ref : 822804004</b> Foot satin Janome St. 6000</p> <p><b>077.822.804</b></p>
 <p><b>Ref : 822808008</b> Foot overcast Janome 6000-8000 "M"</p> <p><b>077.822.808</b></p>	 <p><b>Ref : 822820006</b> Foot darning Janome 2000-7500</p> <p><b>077.822.820</b></p>	 <p><b>Ref : 823801004</b> Foot straight stitch Janome 6000 "K"</p> <p><b>077.823.801</b></p>

**PERSVOETEN - PIEDS PRESSEUR - PRESSER FEET FOR JANOME TOP LOAD 2000-11000**

 <p><b>Ref : 823803006</b>        = 820811008        Janome 2000-9000</p> <p><b>077.823.803</b></p>	 <p><b>Ref : 825510021</b>        = 820506007        = 822508005        Foot ZZ Janome 6000 "A"</p> <p><b>077.825.510</b></p>	 <p><b>Ref : 825817009</b>        Foot blindhem        Janome 7000, 8000 "G"</p> <p><b>077.825.817</b></p>
 <p><b>Ref : 825822007</b>        = 830823004        Foot buttonhole        Janome 4-step 7000, 7500</p> <p><b>077.825.822</b></p>	 <p><b>Ref : 830038004</b>        Foot shank        Janome 8000 series        Fits snap-on</p> <p><b>077.830.038</b></p>	 <p><b>Ref : 830810008</b>        Foot embroidery        Janome 8000, 9000 "P"</p> <p><b>077.830.810</b></p>
 <p><b>Ref : 832427103</b>        Foot open toe        Janome 2000-9000</p> <p><b>077.832.427</b></p>	 <p><b>Ref : P60434</b>        Foot darning        Janome giant 5700, 8000, 9000, 10000</p> <p><b>077.060.434</b></p>	 <p><b>Ref : P60437</b>        Foot darning open toe        Janome 5700, 8000, 9000, 10000</p> <p><b>077.060.437</b></p>
 <p><b>Ref : P60460</b>        Foot weaving yarn low, works on Janome 2000-75000. Sew yarns up to 1/8, one two, three in a row simultaneously by simply adj. the zigzag width.</p> <p><b>077.060.460</b></p>	 <p><b>Ref : P60494</b>        Foot quilting Janome ditch (edge joint) top loading. It sew top stitch, edge stitch and join stitch.</p> <p><b>077.060.494</b></p>	 <p><b>Ref : P60496</b>        Foot sequins Singer Quantum, Janome all</p> <p><b>077.060.496</b></p>
 <p><b>Ref : 200001100</b>        Binder foot        Janome Top Loading        For sewing purchased bias tapes (narrow) or self-made bias strips in one sewing step.</p> <p><b>077.201.100</b></p>	 <p><b>Ref : 200208109</b>        Cording foot        Janome My Lock 134D-204D-634D-644D-734D-744D</p> <p><b>077.208.109</b></p>	 <p><b>Ref : 820817015</b>        Adjustable blindhem foot        Janome 6000G        Has adjustable guide for machines that are equipped with variable needle positions.</p> <p><b>077.820.817</b></p>
 <p><b>Ref : 832523007</b>        Zigzag foot        Janome 5000, 9000</p> <p><b>077.832.523</b></p>	 <p><b>Ref : 941851000</b>        Teflon foot        Janome 6000</p> <p><b>077.941.851</b></p>	 <p><b>Ref : 608590</b>        Elasticator foot        Janome 234-334-134D-234D-334D-434D-534D        Pfaff 603-604-794-795-796</p> <p><b>077.608.590</b></p>
 <p><b>Ref : 340524</b>        Blindhem foot        Janome 234-334-MyLock 134D/234D/334D/434D/534D        Pfaff 603-604-794-795-796-797</p> <p><b>077.340.524</b></p>	 <p><b>Ref : 200207108</b>        Cording foot        Janome My Lock 134D-204D-634D-644D-734D-744D</p> <p><b>077.207.108</b></p>	 <p><b>Ref : 200333001</b>        Concealed zipper foot        Janome Top Load</p> <p><b>077.333.001</b></p>
 <p><b>Ref : P60411</b>        Free motion guide foot        Janome darning MC10000-MC11000-MC5700-MC8000-MC9000</p> <p><b>077.060.411</b></p>	 <p><b>Ref : P60453</b>        Deluxe walking foot        Janome MC10000-MC11000-MC5700-MC8000-MC9000-MC9500-MC9700</p> <p><b>077.060.453</b></p>	 <p><b>Ref : P60454</b>        Deluxe walking foot        Janome 2000-7</p> <p><b>077.060.454</b></p>
 <p><b>Ref : P60490</b>        Welting foot        Singer double Quantum CXL-LE-XL1</p> <p><b>077.060.490</b></p>	 <p><b>Ref : P60495</b>        Beading foot        Singer Quantum, 2.5/4mm (set)        Singer CXL-LE-XL1</p> <p><b>077.060.495</b></p>	 <p><b>Ref : P60499</b>        Roller foot        Singer Quantum        Janome</p> <p><b>077.060.499</b></p>
 <p><b>Ref : P60502</b>        Shirring foot        Double Janome Top Loading</p> <p><b>077.060.502</b></p>	 <p><b>Ref : P60779</b>        Embroidery foot        Open toe Quantum, Janome MC8000-MC9000        Singer Quantum CXL-Quantum LE-Quantum XL1</p> <p><b>077.060.779</b></p>	 <p><b>Ref : P60931</b>        Velvet foot - low        Janome Top Loading</p> <p><b>077.060.931</b></p>